STAK50H CONNECTOR SYSTEM APPLICATION SPECIFICATION

1.0 SCOPE:

This procedure applies to all part numbers with the series 160014, 160026, 160027, 160028 and 160029

2.0 PRODUCT DESCRIPTION:

- 27way / 28way connectors contain up to eight 1.2mm receptacle terminal locations and twentyone 0.50mm receptacle terminal locations. (depopulations available)
- 12way connector contains four 2.8mm receptacle terminal locations and eight 1.2mm receptacle terminal locations.
- 25way connector contains four 2.8mm receptacle terminal locations and twenty-one 0.50mm receptacle terminal locations.
- 32way connector contains four 1.2mm receptacle terminal locations and twenty-eight 0.50mm receptacle terminal locations.
- 4 polarization options for each connector configuration
- Wire range per SAE/J1128 Thin Wall Insulation
 - 0.5 terminals 0.13mm² 0.35mm² (1.3mm MAXIMUM OUTSIDE DIAMETER PER TE TERMINAL CAVITY SPECIFICATION C-2272306-C)
 - \circ 1.2 terminals 0.5mm² 1.5mm²
 - \circ 2.8 terminals 0.5mm² 2.5mm²

• Utilizes the following terminals:

- 0.5 Molex TAK50 Terminals
 - TAK Family (0.5mm)
 - PN: 200096-0101, Tin Plating, Wire Gage: 0.35
 - PN: 200096-0201, Tin Plating, Wire Gage: 0.13
- o 0.5 NanoMQS Drawing
 - TE Generation50 Locking Lance = C-2272196
- 1.2 MCON Drawing
 - JST MSA1.2 = CT0-00041-410
 - Delphi OCS1.2 = 13543112



- o 2.8 MCP Drawing
 - TE AMP MCP2.8 = C-1355036
 - Delphi CTS2.8 = 15457850

REVISION: C1	<u>ECR/ECN INFORMATION:</u> <u>EC No:</u> 10906817 <u>DATE:</u> 2018-JUNE-06	TITLE: Applic	H Connector Syst cation Specificatio	tem on	<u>SHEET No.</u> 1 of 29
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	'ED BY:
AS	-160014-001	Jacob Burgio	Jim Condon	Kurt De	ekoski
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC					

Application Specification



Receptacle Connectors





160029 – 27way

160014 – 28way

160028 – 32way



160026 – 12way



160027 – 25way

REVISION:	ECR/ECN INFORMATION:			1	SHEET No.	
C1	EC No: 10906817	STAK50 Applie	Application Specification			
	DATE: 2018-JUNE-06	Application Specification 2 of 2				
DOCUMENT	NUMBER:	CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	<u>'ED BY:</u>	
AS-160014-001		Jacob Burgio	Jim Condon Kurt Dekoski		ekoski	
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC						

molex Application Specification





56way Header Assembly

2, 28way Pockets Reflow Solder Process



5 Pocket Hybrid Header Assembly

2, 12way Pockets 2, 25way Pockets 1, 27way Pocket Wave Solder Process



8 Rocket Hybrid Header Assembly 4, 32way Pockets 2, 25way Pockets 2, 28way Pockets

Wave Solder Process

REVISION:	ECR/ECN INFORMATION:	TITLE:			SHEET No.
<u>C1</u>	<u>EC No:</u> 10906817	STAK50H Connector System Application Specification		tem	2 ~ 20
C1	<u>DATE:</u> 2018-JUNE-06		3 Of 29		
DOCUMENT	NUMBER:	CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	/ED BY:
AS-160014-001		Jacob Burgio	Jim Condon	Kurt De	ekoski
TEMPLATE FILENAME APPLICATION SPECISIZE AIV. 1) DOC					

3.0 REFERENCE DOCUMENTS:

AS	5-160014-001	Jacob Burgio	Jim Condon	Kurt Dekoski
DOCUMENT	NUMBER:	CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:
C1	DATE: 2018-JUNE-06	Appl	ication Specificatio	n 4 of
		STAK5	50H Connector Syst	em
		Гтіті г .		
	*WDCs are US	SCAR-25 Compliant	APPRU	
	*Dress Cover	B (for 12, 25 way) 16	600300003HSD	
	*Dress Covers	A (for 27, 28, 32 wav) 16	500300002 - SD	
	Packaying - o	Bay neader Fr	N-31302-276	
	Packaging – 2 Packaging – 5 Packaging	Bay Header Pl Bay Header Pl Bay Header Pl	K-31302-235 K-31302-278 K-31202-278	
	Packaging – Conne	ectors Pl	K-31302-266	
	12way Interfac 25way Interfac	ce SI ce SI	D-160026-002 D-160027-002	
	28way Interfac 32way Interfac	ce SI ce SI	D-160014-002 D-160028-002	
	27way Interfac	ce SI	D-160029-002	
	2 Bay Header 5 Bay Header 8 Bay Header	SI 16 16	D-160013-0001 500370002 - RSD 500250003 - RSD	
	12way Conneo 25way Conneo	ctor SI ctor SI	D-160026-0001 D-160027-0001	
	27way Conneo 28way Conneo 32way Conneo	ctor SI ctor SI ctor SI	D-160014-0001 D-160014-0001 D-160028-0001	
	Connector Product Connector Applicat Header Application	SpecificationPSion SpecificationASSpecificationAS	S-160014-001 S-160014-001 S-160013-001	

Kurt Dekoski TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC

SHEET No.

4 of 29

Application Specification

4.0 PROCEDURE

4.1 GENERAL REQUIREMENTS:

A. Connector "As Shipped"

Connector ISL shown in "as shipped" condition (open) the ISL must remain in the open position until all circuits are loaded







B. ISL position

ISL must be in pre-lock position to populate the connector or remove terminals. If during shipping the Connector ISL moves from its pre-lock position. Simply slide a small flat head screwdriver (2.4 - 3.5 mm) behind wall of the ISL and pry to open the ISL

If the ISL or housing is damaged in any way do not use the connector!!!



REVISION:	ECR/ECN INFORMATION:			SHEET No.		
C1	EC No: 10906817	STAK5U Appli	Application Specification			
	<u>DATE:</u> 2018-JUNE-06		3 of 29			
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	ED BY:	
AS-160014-001		Jacob Burgio	Jim Condon	Kurt Dekoski		
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC						

4.2 ASSEMBLY INSTRUCTIONS:

A. Terminal Installation:

With ISL still in pre-lock position, orient the terminal to the rear of the connector as shown below. Grip the wire no less than 20 mm behind the terminal insulation crimp and insert it through the appropriate circuit opening. If resistance is encountered, retract the terminal and adjust the angle of insertion. Continue inserting the terminal until it stops and locks up on the lock finger with an audible click or tactile feedback...

ISL MUST BE IN OPEN POSITION TO POPULATE CONNECTOR

0.5 Terminals

molex





1.2 Terminals





REVISION:	ECR/ECN INFORMATION:			SHEET No.		
C1	<u>EC No:</u> 10906817	STAK50	STAK50H Connector System Application Specification			
	<u>DATE:</u> 2018-JUNE-06		0 01 29			
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	/ED BY:	
AS-160014-001		Jacob Burgio	Jim Condon	Kurt De	ekoski	

TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC

Application Specification

2.8 Terminals





Note: Installing the terminal correctly will have a low effort Incorrectly installing a terminal (rotated out of position) will lead to high effort and wire buckle



Terminal installed correctly



Terminal installed incorrectly

REVISION: C1	ECR/ECN INFORMATION: EC No: 10906817 DATE: 2018-JUNE-06	TITLE: STAK50 Applic	<u>SHEET No.</u> 7 of 29		
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROV	ED BY:
AS	-160014-001	Jacob Burgio	Jim Condon	Kurt De	ekoski
		-	TEMPLATE FILENAME	: APPLICATION_SPEC	[SIZE_A](V.1).DOC

Application Specification

B. Seating the ISL

Prior to closing the ISL, a visual check is recommended to confirm that all of the terminals are seated properly and in the correct position. Once all terminals are installed, close the ISL by placing your thumb and forefinger on the ISL and the connector side opposite of the ISL and apply a gentle force







REVISION:	ECR/ECN INFORMATION:	TITLE:			SHEET No.
C1	<u>EC No:</u> 10906817	STAK50H Connector System		tem	0.(00
C 1	<u>DATE:</u> 2018-JUNE-06	Аррис	8 of 29		
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPRO\	/ED BY:
AS-160014-001		Jacob Burgio	Jim Condon	Kurt Dekoski	
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC					

Application Specification



TPA in the fully seated position

C. Detecting a partially installed terminal

The ISL will not close with a partially installed terminal. If the ISL will not close, confirm that all terminals are fully installed. Leaving the connector in this state will not allow the operator to mate the connector to the header.

Do not force the ISL closed! Damage to the terminal and the ISL will occur!



REVISION:	ECR/ECN INFORMATION:				SHEET No.			
C1	<u>EC No:</u> 10906817	Application Specification		tem	0 of 20			
CI	DATE: 2018-JUNE-06	Аррік	Application Specification					
DOCUMENT	<u>NUMBER:</u>	CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	'ED BY:			
AS-160014-001		Jacob Burgio	Jacob Burgio Jim Condon Kurt Dekoski		ekoski			
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC								

D. Wire Dress Cover (WDC) installation

molex

After completing the terminal/connector assembly, the Wire Dress Cover can be added to the assembly.

Start by forming the wires away from the connector latch



Install the WDC at an angle with the lock features of the WDC engaging the pockets on either side of the latch. Rotate the WDC over the wires to the final lock position.



REVISION:	ECR/ECN INFORMATION:			1 a	SHEET No.	
C1	EC No: 10906817	STAK5U Applie	Application Specification			
	DATE: 2018-JUNE-06		Application Specification			
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	/ED BY:	
AS-160014-001		Jacob Burgio	Jim Condon	Kurt De	ekoski	

TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC

Application Specification



Application Specification

Dress the wires in the desired direction and secure them to the WDC using plastic wire zip tie with a maximum width of 2.5mm

Secure wire tie, making sure it stays on top of WDC behind its protective step rib



Make sure the wires are protected and don't get damaged while securing with the zip tie



REVISION: ECR/ECN INFORMATION: TITLE: SHEET No. **STAK50H Connector System** EC No: 10906817 **C1 Application Specification** 12 of 29 DATE: 2018-JUNE-06 DOCUMENT NUMBER: CREATED / REVISED BY: CHECKED BY: APPROVED BY: AS-160014-001 Jacob Burgio Jim Condon Kurt Dekoski

TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC

Application Specification

Trim the wire zip tie as desired assuring no damage caused to the wires







E. Connector Mating

molex

To properly mate the connector, first note and align connector keying features, from receptacle connector to mating header.

Begin sliding the receptacle connector assembly into the header assembly and press firmly until you hear an audible click.





Keying features

If resistance is encountered, confirm the terminals are fully installed and the ISL is seated. Do not force the connector! Damage to the header, connector, or terminal will occur!



F. Connector mating with the optional CPA Align the keying features and push evenly on the connector body. Do not push on the CPA during the connector mating process!



After mating the connector, push on the CPA to engage.



AS-160014-001

molex

Jacob Burgio

Jim Condon

Kurt Dekoski

TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC

Application Specification





4.3 REMOVAL INSTRUCTIONS

A. Un-mating the connector

To un-mate the connector, push the connector and header together to unload the latch system



REVISION:	ECR/ECN INFORMATION:				SHEET No.
C1	EC No: 10906817	STAK50H Connector System		tem	16 - (20
CI	<u>DATE:</u> 2018-JUNE-06	Аррік	10 of 29		
DOCUMENT	NUMBER:	CREATED / REVISED BY:	CHECKED BY:	APPRO\	/ED BY:
AS-160014-001 Jacob Burgio Jim Condon		Jim Condon	Kurt De	ekoski	
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC					

Application Specification

While depressing the connector latch, gently pull the connector from the header



B. Un-mating the connector with the optional CPA Using a fingertip, gently pry the CPA to the un-lock position





REVISION:	ECR/ECN INFORMATION:				SHEET No.
C1	EC No: 10906817	STAK50H Connector System		tem	17 of 20
CI	DATE: 2018-JUNE-06		11 01 29		
DOCUMENT	<u>NUMBER:</u>	CREATED / REVISED BY:	CHECKED BY:	<u>APPROV</u>	/ED BY:
AS-160014-001		Jacob Burgio	Jim Condon	Jim Condon Kurt Dekoski	
TEMPLATE FILENAME: APPLICATION SPECISIZE AI(V.1).DOC					

Application Specification

Push the connector and the header together to un-load the latch system



While depressing the connector latch, gently pull the connector from the header



C. Removing the Wire Dress Cover (WDC) Remove the plastic wire tie using a pair of side cutters. The wire tie MUST be cut above the wire dress tab to prevent damage to the wires!

molex



Using a small, flat tip screwdriver (2.4 - 3.5 mm wide maximum), release the retention features of the WDC the side of the connector opposite of the latch



Application Specification

Lift the WDC off the connector assembly



D. Opening the ISL

Slide a small flat tip screwdriver (2.4 – 3.5 mm) under the ISL and gently pry to open the ISL



REVISION:	ECR/ECN INFORMATION:	TITLE: STAK50H Connector System		SHEET No.	
C1	<u>EC No:</u> 10906817			20 of 20	
	DATE: 2018-JUNE-06				
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:	
AS-160014-001		Jacob Burgio	Jim Condon	Kurt Dekoski	
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC					

4.4 TERMINAL SERVICING

molex

With the ISL in open position, use the identified tool gently insert tool to depress the terminal lock feature. Once the lock feature is released, pull on the terminal to remove it from the housing.

Connector components may be damaged during servicing, inspect the terminal, housing, and lock finger for damage. Components must be replaced if damaged.

0.5mm Terminals Molex Tool #: 638247500





Pick Size 0.35mm to 0.40mm Square or Diameter



TERMINAL EXTRACTION TOOL AREA





Application Specification				

AS-160014-001

DOCUMENT NUMBER:

C1

EC No: 10906817

DATE: 2018-JUNE-06

<u>CREATED / REVISED BY:</u> Jacob Burgio

CHECKED BY: Jim Condon APPROVED BY:

Kurt Dekoski

TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC



Application Specification



molex

4.5 TERMINAL PROBING

Pogo Pin Recommendations

0.5mm Terminals

Manufacturer:	Lone Star Industrial
Pin:	LS040R-219
Tip Style:	Small flat
Spring Force	4.7 grams (standard)

This pin is intended to contact the front of the terminal through the servicing hole



Application Specification

2.8mm Terminals

Manufacturer: Pin: Tip Style: Spring Force Lone Star Industrial LS040R-219 Small flat 4.7 grams (standard)

This pin intended to contact the front of the terminal



PENDING APPROVAL

REVISION:	ECR/ECN INFORMATION:		H Connector Sys	tom	SHEET No.
C1	<u>EC No:</u> 10906817	Application Specification		25 of 20	
	<u>DATE:</u> 2018-JUNE-06	Application Specification			23 01 23
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:	
AS-160014-001		Jacob Burgio	Jim Condon	Kurt Dekoski	
TEMPLATE FILENAME: APPLICATION_SPEC[SIZE_A](V.1).DOC					

Application Specification

Probe Patterns

The dimensions shown are for locating the center of the terminal probes in relation to circuit 1 of the connection system







Application Specification

REVISION PAGE:

REVISION	DATE	DESCRIPTION
A	2014/05/06	INITIAL RELEASE
В	2015/09/03	GENERAL UPDATE WITH PICTURES OF PARTS AND ADDED
		CONNECTOR PROBING PATTERNS
С	2015/11/24	CAVITY SPEC INFO INCLUDED FOR 0.5 TERMINALS
C1	2018/06/28	UPDATED TERMINAL INFORMATION – PAGE1
		UPDATED FORMAT – PAGES 2, 3
		UPDATED SECTION 3 WITH NEW WDC PN'S – PAGE 4
		UPDATED NEW WDC VISUALS IN SECTION 4.2.D – PAGES 10 – 13
		UPDATED TERMINAL SERVICE PORT VISUALS – PAGES 21 – 23
		UPDATED REV. TABLE – PAGE 29

NOTE: PLEASE REFER TO MOLEX.COM TO ENSURE THE LATEST REVISION OF THIS DOCUMENT

Example : http://midasweb.global.molex.com:7041/midas/FileDownloadServlet?elid=BZWRAFK6

PENDING APPROVAL

REVISION:	ECR/ECN INFORMATION:			SHEET No.	
C1	<u>EC No:</u> 10906817	Application Specification			29 of 29
	<u>DATE:</u> 2018-JUNE-06				
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:	
AS-160014-001		Jacob Burgio	Jim Condon	Kurt Dekoski	
TEMPLATE FILENAME: APPLICATION SPECISIZE AI(V.1).DOC					